



Minor repairs carried out to brickwork and brickwork to porch clear

New 1.8m high close board timber security fence.

Timber enclosure to existing gas meter.

Existing external doors retained and repaired

New notice boards set into existing recesses.

Chapel Fields Elevation

